

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/29/2018

Submitted Date:

10/30/2018

Document Number:

678302279**FIELD INSPECTION FORM**Loc ID 327151 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------------|---------------------------------|
| , | | COGCCinspections@anadarko.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|--------------|--------|-------------|------------|---------|------------------------|-------------|
| 458527 | TANK BATTERY | AC | 10/29/2018 | | - | HSR Reder 5-13 battery | EI |

General Comment:[inspection of production facilities only. battery is no not on location with well it serves](#)

LocationOverall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: no spills observed at surface

☐ Multiple Spills and Releases?

| | | | |
|--------------------|--------------|-------|--|
| Fencing/: | | | |
| Type | TANK BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|--------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | earthen berm | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | |
|-----------|---|----------|-----------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 1 | 300 BBLS | STEEL AST | | , |
| Comment: | | | | | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficient | | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| | | | | | |
|--------------------|---|----------|---------------------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 1 | <50 BBLs | CONCRETE SUMP/VAULT | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|---------|--|
| Condition | | |
| Other (Content) | | |
| Other (Capacity) | 43 bbls | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|------------------------------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficient | | Adequate |
| Comment: | berms shared with crude tank | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|--|-------|
| Yes/No | | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|-------|------|-------------|---|---------|----|---------------|----|
| Facility ID: | 458527 | Type: | TANK | API Number: | - | Status: | AC | Insp. Status: | EI |

| |
|--|
| |
|--|