

Inspection Photos  
Location Name: McCallum Unit 52  
API: 05-057-06033



**Photo 1. Overview of location taken at entrance facing northeast.**



**Photo 2. Stained soil at wellhead, with rag stuffed around seal.**