

# Interim Reclamation and Stormwater Inspection

October 25, 2018

Operator: VERDAD RESOURCES LLC - #10651

Location ID: 435303

Inspection Document #: 682404109

Weld County, CO

SWNW Section 29 T8N R61W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

**Inspection Photos**  
**Location Name: Gaffney #2-29-8-61**  
**Location ID: 435303**



**Photo 1.** Photo taken from well location. Sign has been updated to reflect current Operator but 2 different Operators are posted. Comply with Rule 210.e.



**Photo 2.** Photo taken from the northern interim area, facing West. Desirable vegetation was observed throughout portions of the interim area. Photo illustrates a wheat grass that may have germinated from the mulch product which was observed throughout the interim area.



Inspection Photos  
Location Name: Gaffney #2-29-8-61  
Location ID: 435303



**Photo 3.** Photo taken from the northern interim area, facing East. See comments under Photo 2.



**Photo 4.** Photo taken from the eastern perimeter of the location, facing South. Photo illustrates undesirable weedy vegetation (Kochia and Russian thistle). Operator shall control and manage weedy vegetation, as this will become weed debris and potentially spread more seeds.

Inspection Photos  
Location Name: Gaffney #2-29-8-61  
Location ID: 435303



**Photo 5.** Photo taken from the eastern perimeter of the location, facing East. See comments under Photo 4.



**Photo 6.** Photo taken from the southern perimeter of the location, facing South. See comments under Photo 2.