

# Interim Reclamation Inspection

October 25, 2018

Operator: RED HAWK PETROLEUM LLC - #10503

Location ID: 431634

Inspection Document #: 682404111

Weld County, CO

NWSW Section 2 T7N R60W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location: Buchner #2-2H  
Location ID: 431634



**Photo 1.** Photo taken from the northwestern interim area, facing East. Appears the Operator mowed the interim area. Little to no desirable vegetation was observed throughout the interim area. Operator will need to perform additional reclamation activities to bring this location into compliance with Rule 1003 standards.

Inspection Photos  
Location: Buchner #2-2H  
Location ID: 431634



**Photo 2.** Photo taken from the northwestern interim area, facing West. See comments under Photo 1.

Inspection Photos  
Location: Buchner #2-2H  
Location ID: 431634



**Photo 3.** Reference photo taken from the northern interim area, facing East. Photo illustrates reference area vegetation to the left of the red line in comparison to the interim reclamation area to the right of the red line.

Inspection Photos  
Location: Buchner #2-2H  
Location ID: 431634



**Photo 5.** Photo taken from the northern interim area, facing South. See comments under Photo 1.



**Photo 6.** Photo taken from the northeastern interim area, facing South. See comments under Photo 1.

Inspection Photos  
Location: Buchner #2-2H  
Location ID: 431634



**Photo 7.** Photo taken from the northeastern interim area, facing South. See comments under Photo 1.



**Photo 8.** Photo taken from the eastern interim area, facing West. See comments under Photo 1.