Inspection Photos
Location Name: Babb 14-14 Location ID 332405 Inspection Date: 10/25/2018

Photo 1 –Babb 14-14 treater sign



Photo 2 - Babb 14-14/Kettl23-3 Tank Battery

Inspection Photos
Location Name: Babb 14-14 Location ID 332405 Inspection Date: 10/25/2018

Photo 3 – Skim tank at Babb 14-4/Kettl 23-3 tank battery

Photo 4 – Produced water pit at Babb 14-4/Kettl 23-3 tank battery