

Inspection Photos

Location Name: 05-103-07182 (GILLAM TRIGOOD GOV'T 14)

Location ID: 314769

Inspection: 679701558



Pump jack location



Battery location

Inspection Photos

Location Name: 05-103-07182 (GILLAM TRIGOOD GOV'T 14)

Location ID: 314769


Inspection: 679701558

Venting gas



Venting casing gas

Venting gas



Venting casing gas



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources