

Inspection Photos

Location Name: 05-103-06358 (CALLISTER GOVERNMENT 4)

Location ID: 314687

Inspection: 679701562



Building located 750' north of well head through which gas is flowing



Well flow line located 200' north of building. Gas movement is audible.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: 05-103-06358 (CALLISTER GOVERNMENT 4)

Location ID: 314687

Inspection: 679701562



Uncapped risers at well head



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources