

Inspection Photos

Location Name: 05-103-08022 (HILL 10-31)

Location ID: 315168

Inspection: 679701567



location



Oily waste on ground next to well head