

# Inspection Photos

Operator: BP Production

API: 05-067-07610

Date: 10/24/2018



**Photo 1. View of the project area from the southwestern corner facing center.**





**Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing with grasses and shrubs such as western wheatgrass (*Pascopyrum smithii*), smooth brome (*Bromus inermis*), and rubber rabbitbrush (*Chrysothamnus nauseosus*).**





**Photo 3. View of the western fill slopes from the southwestern corner facing northward.**





**Photo 4. View of musk thistle in post-flower/fruited condition along the northwestern edge of the working area.**