

Inspection Photos

Operator: BP Production

API: 05-067-05474

Date: 10/24/2018



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is progressing with grasses and shrubs such as western wheatgrass (*Pascopyrum smithii*), Indian ricegrass (*Achnatherum hymenoides*), wild tarragon (*Artemisia dracunculus*), and rubber rabbitbrush (*Chrysothamnus nauseosus*).





Photo 3. View of the western project area from the northwestern corner facing southward.



Photo 4. View of what appears to be former pit area in northeastern project area.



Photo 5. View of area in northeastern project area where erosional channel is forming. Approximately 3 feet wide and deep.



Photo 6. Annual jointed goatgrass (*Aegilops cylindrica*) from spring growing season, growing amongst perennial grasses within the western project area.