

Inspection Photos

Location Name: 05-103-08566 (COLUMBINE SP FED 3-14-4-104)

Location ID: 315477

Inspection: 679701582



Location looking east



Tank without labels



Inspection Photos

Location Name: 05-103-08566 (COLUMBINE SP FED 3-14-4-104)

Location ID: 315477

Inspection: 679701582



Well head



Gas leaking out at well head bolt holes