

Inspection Photo
Jolley KP 442-18
API # 045-20004
Inspection # 689302237



Location Photo #1



Location Photo #2

Inspection Photo
Jolley KP 442-18
API # 045-20004
Inspection # 689302237



Location Photo #3



Location Photo #4

**Inspection Photo
Jolley KP 442-18
API # 045-20004
Inspection # 689302237**



Location Photo #5, debris on location



Location Photo #6, Oily residue down tank side

**Inspection Photo
Jolley KP 442-18
API # 045-20004
Inspection # 689302237**



Location Photo #7, missing capacity on all tanks



Location Photo #8, missing capacity on all tanks

**Inspection Photo
Jolley KP 442-18
API # 045-20004
Inspection # 689302237**



Location Photo #9, unused equipment on location



Location Photo #10, unused equipment



**Inspection Photo
Jolley KP 442-18
API # 045-20004
Inspection # 689302237**



Location Photo #11, trash and debris in battery containment



Location Photo #12, unused pipe in battery containment

**Inspection Photo
Jolley KP 442-18
API # 045-20004
Inspection # 689302237**



Location Photo #13, unused fittings in battery containment.