

Inspection Photo
Jolley KP 423-17
API # 045-17111
Inspection # 689302239



Location Photo #1



Location Photo #2

**Inspection Photo
Jolley KP 423-17
API # 045-17111
Inspection # 689302239**



Location Photo #3,



Location Photo #4

**Inspection Photo
Jolley KP 423-17
API # 045-17111
Inspection # 689302239**



Location Photo #5, missing BBL capacity on all production tanks in the battery



Location Photo #6, missing capacity

**Inspection Photo
Jolley KP 423-17
API # 045-17111
Inspection # 689302239**



Location Photo #7, oil stained ground South edge of location



Location Photo #8, oil stained ground

Inspection Photo
Jolley KP 423-17
API # 045-17111
Inspection # 689302239



Location Photo #9, unmarked flowline