

**Inspection Photo
Savage RWF 521-26
API # 045-15945
Inspection # 689302243**



Location Photo #1



Location Photo #2, uncontrolled weeds on location.

Inspection Photo
Savage RWF 521-26
API # 045-15945
Inspection # 689302243



Location Photo #3, uncontrolled weeds on location.



Location Photo #4, uncontrolled weeds on location

**Inspection Photo
Savage RWF 521-26
API # 045-15945
Inspection # 689302243**



Location Photo #5, uncontrolled weeds on location.




Location Photo #6, uncontrolled weeds on location.

Inspection Photo
Savage RWF 521-26
API # 045-15945
Inspection # 689302243



Location Photo #7, uncontrolled weeds on location.



Location Photo #8, uncontrolled weeds on access road.