

Inspection Photo
Jolley 17-313D
API # 045-15862
Inspection # 689302234



Location Photo #1



Location Photo #2

**Inspection Photo
Jolley 17-313D
API # 045-15862
Inspection # 689302234**




Location Photo #3



Location Photo #4

**Inspection Photo
Jolley 17-313D
API # 045-15862
Inspection # 689302234**



Location Photo #5, unused equipment near meter runs.



Location Photo #6, unused equipment.

**Inspection Photo
Jolley 17-313D
API # 045-15862
Inspection # 689302234**



Location Photo #7, unused equipment on NE corner of separators



Location Photo #8, Unused equipment in tank battery.

**Inspection Photo
Jolley 17-313D
API # 045-15862
Inspection # 689302234**



Location Photo #9, unused equipment on N end of Separators



Location Photo #10, unused gas line in tank battery

**Inspection Photo
Jolley 17-313D
API # 045-15862
Inspection # 689302234**



Location Photo #11, unused black pipe and steel pipe



Location Photo #12, debris on location.

**Inspection Photo
Jolley 17-313D
API # 045-15862
Inspection # 689302234**



Location Photo #13, stored equipment, old batteries, solar panels battery boxes

Location Photo #14, Shed on location, stored equipment.

**Inspection Photo
Jolley 17-313D
API # 045-15862
Inspection # 689302234**



Location Photo #15, Mechanical condition of tank and valves



Location Photo #16, stained oily rock in battery containment.

**Inspection Photo
Jolley 17-313D
API # 045-15862
Inspection # 689302234**



Location Photo #17, Missing BBL capacity on all production tanks.

Location Photo #18, missing BBL capacity on all production tanks.

**Inspection Photo
Jolley 17-313D
API # 045-15862
Inspection # 689302234**



Location Photo #19, Missing tank information.



Location Photo #20, Missing labels on 500 gallon tanks.

**Inspection Photo
Jolley 17-313D
API # 045-15862
Inspection # 689302234**



Location Photo #21, Missing labels on 500 gallon tanks.



Location Photo #22, Unmarked flow line

Inspection Photo
Jolley 17-313D
API # 045-15862
Inspection # 689302234



**Location Photo #23, Dumped stain soil near
back of white Ford truck.**

