

Inspection Photos
Location Name: Becker Ranch #2
Facility ID: 449950



Access pre-disturbance (10/06/2014)



Access road during operations (5/31/2018)

Inspection Photos
Location Name: Becker Ranch #2
Facility ID: 449950



Photo 1 – Significant amount of material stockpiled on site.



Photo 2 – Ludwig #2 operations area, farmer was preparing the soil for spreading at time of inspection.

Inspection Photos
Location Name: Becker Ranch #2
Facility ID: 449950



Photo 3 – Access road tracking

Photo 4 - Access road tracking