

Inspection Photos
Location Name: MSW #1 Spread Field
Location ID: 448329



Photo 1 – Site Photo



Photo 2 – Site Photo; Stockpiled material being spread at time of inspection

Inspection Photos
Location Name: MSW #1 Spread Field
Location ID: 448329



Photo 3 – Perimeter berm covered by weeds; Stormwater controls effective in keeping water/material on-site



Photo 4 – Perimeter berm covered by weeds

Inspection Photos
Location Name: MSW #1 Spread Field
Location ID: 448329



Photo 5 – Perimeter berm beginning to erode on southern end of spread field



Photo 6 – Material being tracked of site

Inspection Photos
Location Name: MSW #1 Spread Field
Location ID: 448329



Photo 7 – Access road



Photo 8 – Access road compared to nearby well site

Inspection Photos
Location Name: MSW #1 Spread Field
Location ID: 448329



Photo 9 – Access road



Photo 10 – Cattle guard on access road beginning to fill with bentonitic material

Inspection Photos
Location Name: MSW #1 Spread Field
Location ID: 448329



Photo 11 – Access road at county road



Photo 12 – Aerial imagery of access road (source: Google Earth - 5/31/2018)