

**Inspection Photos**  
**Location Name: Miller-66N64W /29NWSE**  
**Location #: 330698**



Colorado Oil & Gas Conservation Commission  
40.45523, -104.5716, 1409.0m, 71°  
2018/11/01 02:34:44 PM

**Photo #1**

**Miller 33-29 (API # 05-123-19479) wellsite**

**Shut-In**

*Weeds & oil stain have been remediated*



Colorado Oil & Gas Conservation Commission  
40.45675, -104.57075, 1408.0m, 227°  
2018/11/01 02:42:05 PM

**Photo #2**

**Miller 33-29, 43-29 Battery**

**Unused Meter house - Removed**

