

Inspection Photos
Location Name: Miller-66N64W /29NESE
Location #: 331141



Colorado Oil & Gas Conservation Commission
40.45475, -104.56694, 1405.0m, 301°
2018/11/01 02:24:24 PM

Photo #1

Miller 43-29 (API # 05-123-20223) wellsite

Shut-In

Weeds have been remediated



Colorado Oil & Gas Conservation Commission
40.45675, -104.57075, 1408.0m, 227°
2018/11/01 02:42:05 PM

Photo #2

Miller 33-29, 43-29 Battery

