

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/01/2018

Submitted Date:

11/01/2018

Document Number:

689701995

FIELD INSPECTION FORM

Loc ID 336047 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

30 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

OGCC Operator Number: 16700
Name of Operator: CHEVRON USA INC
Address: 6301 DEAUVILLE BLVD
City: MIDLAND State: TX Zip: 79706

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|----------------|-------------------|---------------------------------|
| Haub, Mike | (970) 697-8385 | MHaub@chevron.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 276275 | WELL | PR | 12/15/2005 | GW | 045-10434 | SKINNER RIDGE 598-25-3 | PR |
| 293971 | WELL | PR | 11/22/2009 | GW | 045-15182 | SKR 598-25-AV-01 | PR |
| 293972 | WELL | PR | 11/20/2009 | GW | 045-15183 | SKR 598-25-AV-03 | PR |
| 293973 | WELL | PR | 11/14/2009 | GW | 045-15184 | SKR 598-25-AV-05 | PR |
| 293974 | WELL | PR | 08/30/2013 | GW | 045-15185 | SKR 598-25-AV-06 | PR |
| 293975 | WELL | PR | 10/11/2009 | GW | 045-15186 | SKR 598-25-AV-02 | PR |
| 293976 | WELL | PR | 08/30/2013 | GW | 045-15187 | SKR 598-25-AV-11 | PR |
| 293977 | WELL | PR | 10/08/2009 | GW | 045-15188 | SKR 598-25-AV-04 | PR |
| 293978 | WELL | PR | 08/30/2013 | GW | 045-15189 | SKR 598-25-AV-08 | PR |
| 293979 | WELL | PR | 12/08/2009 | GW | 045-15190 | SKR 598-25-AV-14 | PR |
| 293980 | WELL | PR | 11/17/2009 | GW | 045-15191 | SKR 598-25-AV-07 | PR |
| 293981 | WELL | PR | 02/01/2011 | GW | 045-15192 | SKR 598-25-AV-15 | PR |
| 293982 | WELL | PR | 08/15/2012 | GW | 045-15193 | SKR 598-25-AV-13 | PR |
| 293985 | WELL | PR | 11/07/2009 | GW | 045-15195 | SKR 598-25-AV-09 | PR |
| 293990 | WELL | PR | 09/30/2009 | GW | 045-15196 | SKR 598-25-AV-10 | PR |
| 293993 | WELL | PR | 12/08/2009 | GW | 045-15197 | SKR 598-25-AV-12 | PR |
| 294087 | WELL | PR | 08/01/2013 | GW | 045-15243 | SKR 598-25-AV-20 | PR |
| 294110 | WELL | PR | 08/07/2015 | GW | 045-15254 | SKR 598-25-AV 19 | PR |
| 294112 | WELL | PR | 02/01/2011 | GW | 045-15255 | SKR 598-25-AV-21 | PR |
| 294113 | WELL | PR | 08/30/2013 | GW | 045-15256 | SKR 598-25-AV-16 | PR |
| 294114 | WELL | PR | 08/30/2013 | GW | 045-15257 | SKR 598-25-AV-22 | PR |
| 294116 | WELL | PR | 02/09/2010 | GW | 045-15258 | SKR 598-25-AV-18 | PR |

| | | | | | | | |
|--------|------|----|------------|----|-----------|------------------|----|
| 294117 | WELL | PR | 10/25/2009 | GW | 045-15259 | SKR 598-25-AV-17 | PR |
|--------|------|----|------------|----|-----------|------------------|----|

General Comment:

Routine FIU General Field Inspection

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|----------------------|-------|--|
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Good Housekeeping:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

| Type | | | | | corrective date |
|----------------------------|---------------------|--|--|-------|-----------------|
| Type: Ancillary equipment | # 4 | | | | |
| Comment: | Chemical containers | | | | |
| Corrective Action: | | | | Date: | |
| Type: Other | # 2 | | | | |
| Comment: | Heaters | | | | |
| Corrective Action: | | | | Date: | |
| Type: Plunger Lift | # 20 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| Type: Horizontal Separator | # 2 | | | | |

| | | | |
|--------------------|-----|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| PRODUCED WATER | 1 | 400 BBLs | STEEL AST | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|-------|--|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | Date: | |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|-----------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 276275 | Type: | WELL | API Number: | 045-10434 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 293971 | Type: | WELL | API Number: | 045-15182 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 293972 | Type: | WELL | API Number: | 045-15183 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 293973 | Type: | WELL | API Number: | 045-15184 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 293974 | Type: | WELL | API Number: | 045-15185 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 293975 | Type: | WELL | API Number: | 045-15186 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 293976 | Type: | WELL | API Number: | 045-15187 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 293977 | Type: | WELL | API Number: | 045-15188 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |

| | | | | |
|-------------------------|------------|-----------------------|------------|------------------|
| Facility ID: 293978 | Type: WELL | API Number: 045-15189 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: Producing well | | | | |
| Corrective Action: | | | | Date: |
| Facility ID: 293979 | Type: WELL | API Number: 045-15190 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: Producing well | | | | |
| Corrective Action: | | | | Date: |
| Facility ID: 293980 | Type: WELL | API Number: 045-15191 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: Producing well | | | | |
| Corrective Action: | | | | Date: |
| Facility ID: 293981 | Type: WELL | API Number: 045-15192 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: Producing well | | | | |
| Corrective Action: | | | | Date: |
| Facility ID: 293982 | Type: WELL | API Number: 045-15193 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: Producing well | | | | |
| Corrective Action: | | | | Date: |
| Facility ID: 293985 | Type: WELL | API Number: 045-15195 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: Producing well | | | | |
| Corrective Action: | | | | Date: |
| Facility ID: 293990 | Type: WELL | API Number: 045-15196 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: Producing well | | | | |
| Corrective Action: | | | | Date: |
| Facility ID: 293993 | Type: WELL | API Number: 045-15197 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: Producing well | | | | |
| Corrective Action: | | | | Date: |

| | | | | |
|-----------------------|----------------|-----------------------|------------|------------------|
| Facility ID: 294087 | Type: WELL | API Number: 045-15243 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | Producing well | | | |
| Corrective Action: | | | Date: | |
| Facility ID: 294110 | Type: WELL | API Number: 045-15254 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | Producing well | | | |
| Corrective Action: | | | Date: | |
| Facility ID: 294112 | Type: WELL | API Number: 045-15255 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | Producing well | | | |
| Corrective Action: | | | Date: | |
| Facility ID: 294113 | Type: WELL | API Number: 045-15256 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | Producing well | | | |
| Corrective Action: | | | Date: | |
| Facility ID: 294114 | Type: WELL | API Number: 045-15257 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | Producing well | | | |
| Corrective Action: | | | Date: | |
| Facility ID: 294116 | Type: WELL | API Number: 045-15258 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | Producing well | | | |
| Corrective Action: | | | Date: | |
| Facility ID: 294117 | Type: WELL | API Number: 045-15259 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | Producing well | | | |
| Corrective Action: | | | Date: | |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------------------------------------|
| | | | | Material Handling And Spill Prevention | Pass | Secodary containment under containers |
| | | Ditches | Pass | | | |
| | | Compaction | Pass | | | |
| Ditches | Pass | | | | | |
| | | Culverts | Pass | | | |
| | | | | Vehicle Tracking | Pass | Speed limits set on lease road |
| Check Dams | Pass | | | | | |
| Compaction | Pass | | | | | |
| | | Gravel | Pass | | | |
| Berms | Pass | | | | | |
| Gravel | Pass | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------|---|
| 689701996 | Inspection 689701995 photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4630495 |