

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION
Department of Natural Resources
Suite 380, Logan Tower Building
1580 Logan Street
Denver, Colorado 80203

PHILLIPS PETR. CO.
ATTN: MERRY WIDIKER
P.O. BOX 2926
CASPER, WYO. 82602

Lease REDEISS
Field PLEASANT RIDGE
County MORGAN
Location 18-1N-56W

Gentlemen:

An inspection was made of the lease(s) shown above. The following conditions were observed to exist at the time of the inspection:

- ☒ Oil accumulation on the water in the retaining pit.
- ☐ Skim pit in need of repairs.
- ☐ Skim pit or tank should be constructed.
- ☐ No. I.D. number on tank.

Remarks: _____

The above condition(s) should be corrected immediately. Any surface accumulation of oil in the retaining pits must be cleaned off within ten (10) days after receipt of this notice (Rule 328), and a report submitted to this office within thirty (30) days after the work was accomplished, advising us of the date and manner in which the correction was made. Any person who fails to comply with this request is in violation of this Commission's Rules and Regulations and is subject to the penalties as provided for under 34-6-121 of the Oil and Gas Conservation Act.

William R. Smith
William R. Smith, Director

12
JSK

LEASE INSPECTION FORM

Operator PHILLIPS | CARDINAL Date 10/28/86
Lease Name & No. REDEISS #2 | REDEISS #2 Field PLEASANT RIDGE
Tank Battery No. 1N-56-K-18 County MORGAN
Location _____ Legal Description _____

Type of Inspection PIT

Water Inflow _____ (Bbls. Per Day)

RESULTS OF INSPECTION

(Est. Pit Dimensions, CVD, Lined, Oil on Surface, etc.)

Type of Tank

SKIM TANK 1-300 BBL STEEL

Pit No. 1 HT + LINE HEATER

Pit No. 2 60 X 80, OPEN, UNLINED, 20% OIL
ACTIVE GELSER

Pit No. 3 _____

ADDITIONAL PITS _____

CONDITION OF LEASE (Describe - Oil CVD. or Sat. Gr., Any Leaking, Safety Conditions, Etc.)

PUMPJACK OPERATIONS

T-B FACILITY (INCLUDING PITS) SHARED W/ CARDINAL REDEISS LEASE TO S.

RECOMMENDED ACTION (If Required) NO CL/D FROM PIT

INSPECTOR JSK