

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/02/2018

Submitted Date:

11/02/2018

Document Number:

689702006**FIELD INSPECTION FORM**Loc ID 334353 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:20 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
COGCC, Laramie	970-248-0497	cogccnotifications@laramie-energy.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
279009	WELL	PR	02/01/2015	GW	077-08935	MCDANIEL 2-8	PR
279010	WELL	SI	06/01/2018	GW	077-08936	MCDANIEL 2-7	PR
279011	WELL	PR	10/01/2013	GW	077-08937	MCDANIEL 2-2	PR
279013	WELL	SI	06/01/2018	GW	077-08938	MCDANIEL 2-1	PR
289822	WELL	PR	01/20/2016	GW	077-09257	MCDANIEL FEDERAL 1-4.5	PR
291509	WELL	PR	03/17/2009	GW	077-09349	MCDANIEL 2-7A	PR
291511	WELL	PR	04/17/2012	GW	077-09348	MCDANIEL 2-7B	PR
291513	WELL	PR	06/01/2018	GW	077-09347	MCDANIEL 2-8A	PR
291515	WELL	PR	06/01/2014	GW	077-09346	MCDANIEL 2-8B	PR
291516	WELL	PR	11/20/2008	GW	077-09345	MCDANIEL 2-2C	PR
291517	WELL	PR	06/30/2008	GW	077-09344	MCDANIEL 2-2B	PR
291519	WELL	PR	10/16/2009	GW	077-09343	MCDANIEL 2-2A	PR
291520	WELL	PR	01/14/2016	GW	077-09342	MCDANIEL 2-1C	PR
291521	WELL	PR	07/16/2009	GW	077-09341	MCDANIEL 2-1A	PR
291522	WELL	PR	02/04/2015	GW	077-09340	MCDANIEL 2-1B	PR
291989	WELL	PR	07/22/2008	GW	077-09378	MCDANIEL 2-8C	PR
291990	WELL	PR	10/01/2013	GW	077-09379	MCDANIEL 2-7C	PR

General Comment:[Routine FIU General Field Inspection](#)

Location

Lease Road:			
Type			
comment:			
Corrective ActionL		Date:	

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-248-0497

Corrective Action:

Date: _____

Good Housekeeping:			
Type			
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 17		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			

Corrective Action:		Date:	
Type: Vertical Heated Separator	# 17		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	279009	Type:	WELL	API Number:	077-08935	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	279010	Type:	WELL	API Number:	077-08936	Status:	SI	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	279011	Type:	WELL	API Number:	077-08937	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	279013	Type:	WELL	API Number:	077-08938	Status:	SI	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	289822	Type:	WELL	API Number:	077-09257	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	291509	Type:	WELL	API Number:	077-09349	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	291511	Type:	WELL	API Number:	077-09348	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	291513	Type:	WELL	API Number:	077-09347	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

Facility ID:	291515	Type:	WELL	API Number:	077-09346	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	291516	Type:	WELL	API Number:	077-09345	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	291517	Type:	WELL	API Number:	077-09344	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	291519	Type:	WELL	API Number:	077-09343	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	291520	Type:	WELL	API Number:	077-09342	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	291521	Type:	WELL	API Number:	077-09341	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	291522	Type:	WELL	API Number:	077-09340	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	291989	Type:	WELL	API Number:	077-09378	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing								
Corrective Action:						Date:			

Facility ID:	291990	Type:	WELL	API Number:	077-09379	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well			
Comment:	Producing		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Berms	Pass					
		Compaction	Pass			
		Gravel	Pass			
		Ditches	Pass			
		Culverts	Pass			
Waddles	Pass					
Ditches	Pass					
Check Dams	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689702008	Inspection 68702006 Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4632239