

Inspection Photos

Location Name: 05-103-07837 (LOWER HORSE DRAW UNIT 2123)

Location ID: 315056

Inspection: 679701629



Location looking north



Tank missing capacity sign



Inspection Photos

Location Name: 05-103-07837 (LOWER HORSE DRAW UNIT 2123)

Location ID: 315056

Inspection: 679701629



All deadman unmarked. Cattle in area.

