

Inspection Photos

Location Name: 05-103-07880 (C&K 1-6)

Location ID: 315079

Inspection: 679701633



Location looking north



Weeds next to pump jack



Inspection Photos

Location Name: 05-103-07880 (C&K 1-6)

Location ID: 315079

Inspection: 679701633



Gas leaking at well head photo 1

Gas leaking



Gas leaking at well head photo 2

Gas leaking

Inspection Photos

Location Name: 05-103-07880 (C&K 1-6)

Location ID: 315079

Inspection: 679701633



Missing NFPA label and operator



Unmarker riser next to tank



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: 05-103-07880 (C&K 1-6)

Location ID: 315079

Inspection: 679701633



Unused timbers next to pump jack



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources