

**Inspection Photos**  
**Location Name: 05-103-08625 (C&K 2-24)**  
**Location ID: 315509**  
**Inspection: 679701639**



**Location looking north**



**Uncapped risers next to meter building**

# Inspection Photos

Location Name: 05-103-08625 (C&K 2-24)

Location ID: 315509

Inspection: 679701639

Gas leaking



Gas leaking at well head – photo 1

Gas leaking at well head – photo 2

Gas leaking

# Inspection Photos

Location Name: 05-103-08625 (C&K 2-24)

Location ID: 315509

Inspection: 679701639



Only sign on location

