



Company Representative Performing the Test: Paul Herring

Equipment	Height		Test Start Date	Day 2	Day 3	Test Finish Date	Pass	Fail	Remark
	Start	Finish							
North Water Pro	5' 6"	5' 6"	10/17/2018	10/18/2018	10/19/2018	10/20/2018	X		Water vault showed no sign of leakage during four days of testing