

Inspection Photo
Savage RWF 331-26
API # 045-17336
Inspection # 689302245



Location Photo #1

Location Photo #2



**Inspection Photo
Savage RWF 331-26
API # 045-17336
Inspection # 689302245**



Location Photo #3, non legible wellhead sign

Location Photo #4, non legible wellhead sign.

Inspection Photo
Savage RWF 331-26
API # 045-17336
Inspection # 689302245



Location Photo #5, uncontrolled weeds near separator and tank battery.



Location Photo #6, unused equipment cleaned up.

Inspection Photo
Savage RWF 331-26
API # 045-17336
Inspection # 689302245

Location Photo #1

Location Photo #2

