

**Inspection Photo  
Rifle Boulton 1  
API # 045-06127  
Inspection # 689302263**



**Location Photo #1**

**Location Photo #2**

**Inspection Photo  
Rifle Boulton 1  
API # 045-06127  
Inspection # 689302263**



**Location Photo #3 uncontrolled weeds**



**Location Photo #4, uncontrolled weeds in tank battery area.**

**Inspection Photo  
Rifle Boulton 1  
API # 045-06127  
Inspection # 689302263**



**Location Photo #5, Missing wellhead sign**



**Location Photo #6, flow line coming from wellhead.**

**Inspection Photo  
Rifle Boulton 1  
API # 045-06127  
Inspection # 689302263**



**Location Photo #7 Flow line coming from wellhead plumbed into tank.**



**Location Photo #8, unmarked flowlines, unused equipment.**