

Inspection Photos
Location Name: Rabbit Ears 0681 23
Location ID: 449274



Photo 1. Overview of location taken at entrance facing south.



Photo 2. Open ended loadout hose with no containment.

Inspection Photos
Location Name: Rabbit Ears 0681 23
Location ID: 449274



Photo 3. Rat hole at wellhead.



Photo 4. Trash at wellhead.

Inspection Photos
Location Name: Rabbit Ears 0681 23
Location ID: 449274



Photo 5. Frac sand on location.



Photo 6. Example of drips visible on location/