

Final Reclamation Inspection

October 31, 2018

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

API: 05-123-11518

Inspection Document #: 682404143

Weld County, CO

SWSE Section 1 T6N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: CUDNEY/SANDSTEDT #1
API: 05-123-11518



COGCC GISOnline aerial imagery from 2017 taken during active operations. Operator has failed to perform final reclamation activities (i.e., remove gravel, decompact, seedbed prep and seed) at the tank battery location.

Inspection Photos
Location Name: CUDNEY/SANDSTEDT #1
API: 05-123-11518



Photo 1. Photo taken from the entrance of the well access road, facing West. A vegetative assessment could not be performed because of crop harvest. However, there are obvious areas that do not appear reflective of reference area vegetative levels. Operator may need to perform additional reclamation activities to bring this into compliance.



Photo 2. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: CUDNEY/SANDSTEDT #1
API: 05-123-11518



Photo 3. Photo taken from the eastern tank battery location, facing West. Operator has failed to perform final reclamation activities (i.e., remove gravel, decompact, seedbed prep and seed).



Photo 4. Photo taken from the northern tank battery location, facing West. See comments under Photo 3.

Inspection Photos
Location Name: CUDNEY/SANDSTEDT #1
API: 05-123-11518



Photo 5. Photo taken from the northern tank battery location, facing North. See comments under Photo 3.