

Final Reclamation Inspection

October 31, 2018

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

API: 05-123-11822

Inspection Document #: 682404145

Weld County, CO

SESE Section 11 T6N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: MILLER #1
API: 05-123-11822



COGCC GISOnline aerial imagery from 2017 taken after plugging operations. Operator has failed to perform final reclamation activities (i.e., remove gravel, decompact, seedbed prep and seed) at the well and tank battery location.

Inspection Photos
Location Name: MILLER #1
API: 05-123-11822



Photo 1. Photo taken from the central well and tank battery location, facing South. Operator has failed to perform final reclamation activities (i.e., remove gravel, decompact, seedbed prep and seed).



Photo 2. Photo taken from the southern well and tank battery location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: MILLER #1
API: 05-123-11822



Photo 3. Photo taken from the southern well and tank battery location, facing North. See comments under Photo 1.



Photo 4. Photo taken from the northern well and tank battery location, facing West. See comments under Photo 1.