

# Final Reclamation Inspection

October 31, 2018

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

API: 05-123-11328

Inspection Document #: 682404147

Weld County, CO

NENE Section 15 T6N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: SIMPSON #1  
API: 05-123-11328



COGCC GISOnline aerial imagery from 2017 taken during operations. Operator has failed to perform final reclamation activities (i.e., remove gravel, culvert, decompaction, seedbed prep and seed) at the well and tank battery location, and along the access road.

Inspection Photos  
Location Name: SIMPSON #1  
API: 05-123-11328



**Photo 1.** Photo taken from the northern tank battery location, facing South. Operator has failed to perform final reclamation activities (i.e., remove gravel, decompaction, seedbed prep and seed).



**Photo 2.** Photo taken from the eastern access road, facing West. See comments under Photo 1.



Inspection Photos  
Location Name: SIMPSON #1  
API: 05-123-11328



**Photo 3.** Photo taken from the western access road, facing West. See comments under Photo 1.



**Photo 4.** Photo taken from the well location, facing North. See comments under Photo 1.

Inspection Photos  
Location Name: SIMPSON #1  
API: 05-123-11328



**Photo 5.** Photo taken along a portion of the access road.  
Photo illustrates a culvert that has not been removed.