

Final Reclamation Inspection

October 31, 2018

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

API: 05-123-24097

Inspection Document #: 682404149

Weld County, CO

SWSE Section 11 T6N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: MILLER #34-11
API: 05-123-24097



Photo 1. Photo taken from the well location, facing West. A vegetative assessment could not be performed because of crop harvest.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.