

# Inspection Photos

11/1/2018

Operator: GRAND MESA OPERATING CO - 35080

Location ID: 457667

Inspection Doc. Number: 682504079

Washington County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo taken from the southwest corner of the disturbance area, facing north. Photos 1-11 were taken from each corner of the disturbance (SW, SE, NW, NE). Photo shows perimeter stormwater and erosion control BMPs were not installed prior to or during construction activities.





**Photo 2:**





**Photo 3:**



Inspection Photos  
Operator: GRAND MESA OPERATING CO - 35080  
Location ID: 457667



**Photo 4:**







**Photo 5:**



Inspection Photos  
Operator: GRAND MESA OPERATING CO - 35080  
Location ID: 457667



**Photo 6:**



Inspection Photos  
Operator: GRAND MESA OPERATING CO - 35080  
Location ID: 457667



**Photo 7:**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Doc. Number: 682504079





**Photo 8:**





**Photo 9:**





**Photo 10:**



**Photo 11:**





**Photo 12:** Photo taken from the southwest corner of the disturbance area, facing north. Photos 12-20 were taken from each corner of the disturbance (SW, SE, NW, NE). Photo shows contractor installed surface roughening along the perimeter of the disturbance area after conversations regarding stormwater occurred with the inspector.





**Photo 13:**





**Photo 14:**





**Photo 15:**





**Photo 16:**





**Photo 17:**





**Photo 18:**





**Photo 19:**





**Photo 20:**