

Inspection Photos

11/1/2018

Operator: GRAND MESA OPERATING CO - 35080

Location ID: 453932

Inspection Doc. Number: 682504085

Washington County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the east end of the pump unit, facing west. Photo shows pump.



Photo 2: Photo taken from the east end of the pump unit. Photo shows sign. Sign at well missing operator contact/emergency number.



Photo 3: Photo taken from the east end of the pump unit. Photo shows pipe stored on location. This is equipment that does not appear to be needed for production activities and needs to be removed and properly stored.



Photo 4: Photo taken from the east end of the pump unit, facing east. Photo shows areas disturbed during construction activities, that do not appear to be reasonably needed for production activities, have not yet been reclaimed.



Photo 5: Photo taken from the east end of the location, facing north. Photo shows areas disturbed during construction activities, that do not appear to be reasonably needed for production activities, have not yet been reclaimed. Photos 5-8 also show an overview of the location from south, to west, to north.



Photo 6: Photo taken from the 50th point of the germination transect. Photo shows vegetation over the reclamation area.



Photo 7: Photo taken from the adjacent reference area. Vegetation appears to be predominantly western wheatgrass.



Photo 8:



Photo 9: Photo taken from the north end of the location, facing west. Photo shows drill pit remains open.



Photo 10: Photo taken from the west end of the pad, facing west. Photo shows area of the location where soils appear to have been replaced.



Photo 11: Photo taken from the west end of the pad, facing east. Photo shows area of the location where soils appear to have been replaced.