

Inspection Photos

11/5/2018

Operator: FRITZLER RESOURCES INC - 31257

Location ID: 316908

Inspection Doc. Number: 682504087

Washington County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the northeast end of the pits, facing south. Photo shows area of the pit where water was discharging at the base. Spill appears to have been controlled.



Photo 2: Photo taken from the northeast end of the pits, facing south. Photo shows area of the pit where water was discharging at the base. Spill appears to have been controlled.



Photo 3: Photo taken from the northeast end of the pits, facing east. Photo shows area of the pit where water was discharging at the base. Spill appears to have been controlled.



Photo 4: Photo taken from the northeast end of the pits, facing southwest. Photo shows area of the pit where water was discharging at the base. Spill appears to have been controlled.



Photo 5: Photo taken from the northeast end of the pits, facing west. Photo shows area of the pit where water was discharging at the base. Spill appears to have been controlled, however, cleanup does not appear to have occurred.