

Inspection Photos

11/5/2018

Operator: MURFIN DRILLING COMPANY INC -
61650

Location ID: 458362

Inspection Doc. Number: 682504089
Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the southeast corner of the disturbance area, facing west. Photo shows construction in process. Photo also shows surface roughening has been used as a perimeter stormwater control



Photo 2: Photo taken from the southeast corner of the disturbance area, facing north. Photo shows construction in process. Photo also shows surface roughening has been used as a perimeter stormwater control



Photo 3: Photo taken from the northwest corner of the disturbance area, facing south. Photo shows construction in process. Photo also shows surface roughening has been used as a perimeter stormwater control



Photo 4: Photo taken from the northwest corner of the disturbance area, facing east. Photo shows construction in process. Photo also shows surface roughening has been used as a perimeter stormwater control