

Inspection Photos

11/5/2018

Operator: WIEPKING-FULLERTON ENERGY LLC -
96340

Location ID: 443191

Inspection Doc. Number: 682504096
Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the northwest corner of the location, facing east. Photo shows overview of the reclamation area.



Photo 2: Photo taken from the northwest corner of the location, facing esouth. Photo shows overview of the reclamation area.




Photo 3: Photo taken from the location, facing southeast. Photo shows the “Germination Transect” line.



Photo 4: Photo taken from the 50th point of the transect. Photo shows vegetation over the reclamation area.




Photo 5: Photo taken from the 50th point of the transect, facing northwest. Photo shows vegetation over the reclamation area and transect line. Vegetation over the reclamation area remains predominantly undesirable weedy plant species such as Russian thistle.



Photo 6: Photo taken from the southeast corner of the location, facing north. Photo shows reclamation activities appear to have been conducted on areas no longer reasonable needed for production activities.