



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Oct 31, 2018 9:12:47 AM MDT
Server Receive Date:	Oct 31, 2018 10:25:34 AM MDT
Reference Number:	20181031-1890871458
Location:	US-491, Tohatchi, NM 87325, USA Oct 31, 2018 9:12:56 AM MDT [ <a href="#">View Map</a> ]

## Information

Name	reclamationtablet
Date	Oct 30, 2018
Well Name	SCHOFIELD GAS UNIT A 1
API Number	50670785900
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Seeding Erosion Repairs Other Install Wattles Removed sediment from BMP's

## Picture North to South



## Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



#### Additional photos



#### Completed work description

Old erosion logs were removed and replaced with new ones. The northern slopes were seeded and mulched with a steep slope mulch. An herbicide application was done on Russian knapweed.