



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Oct 31, 2018 10:25:02 AM MDT
Server Receive Date:	Oct 31, 2018 10:25:33 AM MDT
Reference Number:	20181031-1890871456
Location:	3380 Rte 66, Gallup, NM 87301, USA
	Oct 31, 2018 10:25:25 AM MDT [ <a href="#">View Map</a> ]

## Information

Name	reclamationtablet
Date	Oct 26, 2018
Well Name	SPANISH FORK GAS UNIT B 2
API Number	50670880801
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Other Install Wattles Clean Up Weed Debris

## Picture North to South



## Picture South to North



## Picture East to West



Picture West to East



Additional photos



Additional photos



Completed work description

Removed weeds debris around equipment. installed erosion logs on northeast drainage. Herbicide application on Russian knapweed.