



Form Information

Form Name: **Compliance Follow Up Form**
Submitter Name: Reclamation Tablet (reclamationtablet)
Submission Date: Nov 2, 2018 8:52:52 AM MDT
Server Receive Date: Nov 2, 2018 8:53:26 AM MDT
Reference Number: 20181102-1890998713
Location: 557 Airpark Dr, Durango, CO 81303, USA
Nov 2, 2018 8:53:13 AM MDT [[View Map](#)]

Information

Name: reclamationtablet
Date: Nov 1, 2018
Well Name: HOTT GAS UNIT 20-02 1
API Number: 50670662900
Select State: Colorado
Work type: COGCC Inspection AR
Action Complete: Other
Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



Completed work description

treated Russian knapweed in reclamation area

