

**Inspection Photos**  
**Location Name: HSR-FULENWIDER 12-10**  
**Location ID: 320429**



**PHOTO 1: WELLHEAD**



**PHOTO 2: UNUSED EQUIPMENT/ CORRECTIVE ACTION  
REMOVE OR MARK UNUSED RISER**