


## Inspection Photos

Location Name: 05-103-08557 (RANGELY SOUTH FEDERAL 13-1-1-102)

Location ID: 315473

Inspection: 679701660



Location looking south



Location looking southwest



## Inspection Photos

Location Name: 05-103-08557 (RANGELY SOUTH FEDERAL 13-1-1-102)

Location ID: 315473

Inspection: 679701660



**Tank with hole near bottom edge. Tank appears to be out of service.**



**Tank without NFPA label, contents, capacity of 300 bbl, operator, and phone number.**




## Inspection Photos

Location Name: 05-103-08557 (RANGELY SOUTH FEDERAL 13-1-1-102)

Location ID: 315473

Inspection: 679701660



**Bird protector for separator stack lying on ground**