

Inspection Photos

Location Name: 05-103-08999 (TAIGA MOUNTAIN 16-22)

Location ID: 315680

Inspection: 679701664



Location photo looking east



Location photo looking north



Inspection Photos

Location Name: 05-103-08999 (TAIGA MOUNTAIN 16-22)

Location ID: 315680

Inspection: 679701664



Tank battery looking northwest



Gas leaking inside separator




Inspection Photos

Location Name: 05-103-08999 (TAIGA MOUNTAIN 16-22)

Location ID: 315680

Inspection: 679701664

Gas leaking



Well head



Gas leaking at casing valve



Inspection Photos

Location Name: 05-103-08999 (TAIGA MOUNTAIN 16-22)

Location ID: 315680

Inspection: 679701664



Sign missing nearest public road "CR 2"



Tanks missing NFPA label and current phone number.



Inspection Photos

Location Name: 05-103-08999 (TAIGA MOUNTAIN 16-22)

Location ID: 315680

Inspection: 679701664



Weeds on berm and within berm area



Tanks looking southeast

