

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/06/2018

Submitted Date:

11/06/2018

Document Number:

689302287

FIELD INSPECTION FORM

Loc ID 335379 Inspector Name: Holtz, Darin On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
Name of Operator: VANGUARD OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

Findings:

21 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Ghan, Scott	970-744-8128	sghan@vnrenergy.com	SR. EH&S
Aaron, Axelson	230-0926	aaxelson@vnrenergy.com	Sr. Production Foreman

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263512	WELL	PR	04/05/2005	GW	045-08133	BRYNILDSON 13C-20-692	PR
276580	WELL	PR	03/13/2009	GW	045-10488	BRYNILDSON 13B-20-692	PR
276581	WELL	PR	05/31/2005	GW	045-10487	BRYNILDSON 12A-20-692	PR
276741	WELL	PR	03/01/2009	GW	045-10513	BRYNILDSON 13D-20-692	PR
297757	WELL	PR	03/16/2009	GW	045-16952	BRYNILDSON 12C-20-692	PR
297758	WELL	PR	03/06/2009	GW	045-16953	BRYNILDSON 22A-20-692	PR
297759	WELL	PR	03/01/2009	GW	045-16954	BRYNILDSON 22B-20-692	PR
297760	WELL	PR	03/01/2009	GW	045-16955	BRYNILDSON 22C-20-692	PR
297761	WELL	PR	03/11/2009	GW	045-16956	BRYNILDSON 23B-20-692	PR
297762	WELL	PR	03/05/2009	GW	045-16957	BRYNILDSON 23C-20-692	PR
297763	WELL	PR	02/25/2009	GW	045-16958	BRYNILDSON 23D-20-692	PR
297764	WELL	PR	03/10/2009	GW	045-16959	BRYNILDSON 12B-20-692	PR

General Comment:

Routine field inspection.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Emergency Contact Number:			
Comment:	1-800-921-8252		
Corrective Action:		Date:	
Good Housekeeping:			
Type	TRASH		
Comment:			
Corrective Action:		Date:	
Type	WEEDS		
Comment:			
Corrective Action:		Date:	
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Panel gates.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panel fence		
Corrective Action:		Date:	
Equipment:			
Type: Horizontal Heated Separator	# 12		corrective date
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chemical units at wellheads.		
Corrective Action:		Date:	

Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 10		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 12		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	500 BBLs	HEATED STEEL AST		,
Comment:	Centralized battery.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	500 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	YES		
Comment:	Bradenheads valves open to vent.		
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	<u>263512</u>	Type:	<u>WELL</u>	API Number:	<u>045-08133</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift</u>								
Corrective Action:				Date:					
Facility ID:	<u>276580</u>	Type:	<u>WELL</u>	API Number:	<u>045-10488</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift</u>								
Corrective Action:				Date:					
Facility ID:	<u>276581</u>	Type:	<u>WELL</u>	API Number:	<u>045-10487</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift</u>								
Corrective Action:				Date:					
Facility ID:	<u>276741</u>	Type:	<u>WELL</u>	API Number:	<u>045-10513</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift</u>								
Corrective Action:				Date:					
Facility ID:	<u>297757</u>	Type:	<u>WELL</u>	API Number:	<u>045-16952</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift</u>								
Corrective Action:				Date:					
Facility ID:	<u>297758</u>	Type:	<u>WELL</u>	API Number:	<u>045-16953</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift</u>								
Corrective Action:				Date:					
Facility ID:	<u>297759</u>	Type:	<u>WELL</u>	API Number:	<u>045-16954</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift</u>								
Corrective Action:				Date:					
Facility ID:	<u>297760</u>	Type:	<u>WELL</u>	API Number:	<u>045-16955</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>

Producing Well			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	

Facility ID: 297761 Type: WELL API Number: 045-16956 Status: PR Insp. Status: PR

Producing Well			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	

Facility ID: 297762 Type: WELL API Number: 045-16957 Status: PR Insp. Status: PR

Producing Well			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	

Facility ID: 297763 Type: WELL API Number: 045-16958 Status: PR Insp. Status: PR

Producing Well			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	

Facility ID: 297764 Type: WELL API Number: 045-16959 Status: PR Insp. Status: PR

Producing Well			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles						
		Culverts				
		Compaction				
Berms						
Rip Rap						
		Gravel				
Retention Ponds						
Ditches						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302288	Inspection photo 689302288	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4636906