

Inspection Photos

Operator: WPX Energy

API: 05-067-05431

Date: 10/24/2018



Photo 1. View of the project area from eastern edge facing west toward the well head marker (in the background). Revegetation is patchy within the reclamation areas with grasses such as crested wheatgrass (*Agropyron cristatum*), western wheatgrass (*Pascopyrum smithii*), and rubber rabbitbrush (*Chrysothamnus nauseosus*).



Photo 2. View of Russian knapweeds (*Acroptilon repens*) within the northern project area. Approximately 500 individuals observed.



Photo 3. View of musk thistles (*Carduus nutans*) within the central portion of the project area. Approximately 100 individuals observed.



Photo 4. View of BP storage area from the western portion of the project area from the southeastern edge of the fenced storage area facing northwestward.



Photo 5. View of pipe storage north of the BP storage area in the western portion of the project area.



Photo 6. View of the beginning of Transect 1, within the project area facing northward.



Photo 7. View of the beginning of Transect 2, within the reference area facing southward.