

Location Name: Fritzler Resources, Inc. (Produced Water Pit 109572) Spill  
Inspection Date: 11/01/2018



Photo # - 1

View southeast at northeast corner of produced water pit spill area



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Fritzler Resources, Inc. (Produced Water Pit 109572) Spill  
Inspection Date: 11/01/2018



Photo # - 2

View southwest at northeast corner of produced water pit spill area and berm repair



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Location Name: Fritzler Resources, Inc. (Produced Water Pit 109572) Spill  
Inspection Date: 11/01/2018



Photo # - 3

View southeast at northeast corner of produced water pit spill area



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Fritzler Resources, Inc. (Produced Water Pit 109572) Spill  
Inspection Date: 11/01/2018



Photo # - 4

View southwest at northeast corner of produced water pit spill area and berm repair



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Location Name: Fritzler Resources, Inc. (Produced Water Pit 109572) Spill  
Inspection Date: 11/01/2018



Photo # - 5

View east at northeast corner produced water pit berm repair



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Fritzler Resources, Inc. (Produced Water Pit 109572) Spill  
Inspection Date: 11/01/2018



Photo # - 6

View east-northeast at northeast corner produced water pit berm repair and spill area



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Location Name: Fritzler Resources, Inc. (Produced Water Pit 109572) Spill  
Inspection Date: 11/01/2018



Photo # - 7

View northwest at former landfarm area, weeds have been mowed.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Fritzler Resources, Inc. (Produced Water Pit 109572) Spill  
Inspection Date: 11/01/2018



Photo # - 8

View west at former landfarm area, weeds have been mowed.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources