

# *Inspection Photos*

*Loc#335992*

*Operator: Caerus*

*Inspection Number: 692400304*

*Inspection Date: 10/19/2018*





Photo#1:  
Overview of Location from entry to South

October 19, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Loc#335992



Photo#2:  
Areas of Location no longer needed for Use have not been Reclaimed.

October 19, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Loc#335992



Photo#3:  
Areas of Location no longer needed for Use have not been Reclaimed.

October 19, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Loc#335992



Photo#4:

What may be part of installment for old Anchors was noted on West edge of Pad

Photo#5:

October 19, 2018