

# Final Reclamation Inspection

November 6, 2018

Operator: CRESTONE PEAK RESOURCES OPERATING LLC-  
#10633

API: 05-123-08740

Inspection Document #: 682404153

Weld County, CO

SESE Section 31 T1N R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: ADAM TEN #1-A  
API: 05-123-08740



**Photo 1.** Photo taken from the entrance of the access road to the location. Operator shall remove the sign.



**Photo 2.** Photo taken from the entrance of the access to the location, facing North. Operator has failed to perform final reclamation activities (i.e., remove gravel, decompaction, seedbed prep and seed). Reference area vegetation is alfalfa (cropland).



Inspection Photos  
Location Name: ADAM TEN #1-A  
API: 05-123-08740



**Photo 3.** Photo taken from the tank battery location, facing South. Operator has failed to remove all equipment.



**Photo 4.** Photo taken from the eastern tank battery location, facing West. See comments under Photo 2.