

Inspection Photos

Operator: BP America

API: 05-067-07767

Date: 10/30/2018



Photo 1. View of the project area from the southern edge facing northwestward. Revegetation is progressing with intermediate wheatgrass (*Thinopyron intermedium*), sand dropseed (*Sporobolus cryptandrus*), and big sagebrush (*Artemisia tridentata*).



Photo 2. View of the eastern project area from the southeastern corner facing northward.



Photo 3. View of musk thistles (*Carduus nutans*) within the interim reclamation area. Approximately 150 individuals observed.